

## Przegub wahacza 17-PW-06

Renault 11 83>, 19 88>03, 21 94>, Clio 90> Clio II 98>, Kangoo 97>, Megane I 95>03, Thalia 98>, Thalia II 08>, Twingo 93>;

Nissan Kubistar 03>

O.E. 7701468411 FEBI 10640 TRW JBJ761 TC1438



## Przegub wahacza 22-PW-12 prawy

VW Golf IV 97>06, Bora 98>05, New Beetle 02>10, Skoda Octavia 96>10, Seat Leon 99>06, Toledo II 99>06, Audi A3 96>03

O.E. 1J0407366A FEBI 14444 TRW JBJ113 TC825



## Przegub wahacza 22-PW-13 lewy

VW Golf IV 97>06, Bora 98>05, New Beetle 02>10, Skoda Octavia 96>10, Seat Leon 99>06, Toledo II 99>06, Audi A3 96>03

O.E. 1J0407365A FEBI 14440 TRW JBJ377 TC824



## Przegub wahacza 22-PW-14

VW Transporter IV 90>06

od numeru podwozia 70-T-200 000

O.E. 7D0407361 FEBI 18740 TRW JBJ661 TC967



## Łącznik stabilizatora 23-LS-05 przód

Volvo V40 S40 00>04

O.E. 30884179 FEBI 22390 TRW JTS491 TC2095

